



### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:		)	
•		:	Examiner: Robert M. Kunemund
MITSUAKI AMEMIYA		)	
		:	Art Unit: 1722
Appln. No.: 09/487,718		)	
		:	
Filed: January 19, 2000		)	
		:	
For:	APPARATUS AND PROCESS FOR	)	
	PRODUCING CRYSTAL ARTICLE,	:	$C_{\Theta_{Chic}}$
	AND THERMOCOUPLE USED	)	Certificate  AUG 0 2 2006  Of Correction
	THEREIN	:	
		)	of C2 2 <006
U.S. Patent No.: 7,014,707 B2		:	Orrection of the state of the s
		)	SUON
Issued:	March 21, 2006	:	July 27, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

## CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the

Patent and Trademark Office due to mistakes of a clerical, typographical, or minor

character, which were not the fault of the Patent and Trademark Office. A Certificate of

08/01/2006 NBEYENE1 00000028 7014707

Correction form, in duplicate, is enclosed.

01 FC:1811

109.09 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentee Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

582062v1

### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

PATENT NO.

7,014,707 B2

DATED

March 21, 2006

INVENTOR(S) :

MITSUAKI AMEMIYA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 6**

Line 26, "deposit" should read --be deposited--.

### COLUMN 9

Line 52, "is" (second occurrence) should read --are--;.

### COLUMN 10

Line 33, "is continued being descended" should read --continues to descend--;

Line 34, "occure" should read --occur--:

Line 35, "not" should read --not only--; Line 65, "of" should be deleted; and

Line 67, "of" should be deleted.

### COLUMN 12

Line 1, "is escaped" should read --escapes--.

### COLUMN 14

Line 18, "is continued being descended" should read --continues to descend--.

### COLUMN 18

Line 62, "vacuum" should read --in a vacuum--.

### COLUMN 19

Line 30, "vacuum," should read --in a vacuum--; and Line 33, "vacuum" should read --in a vacuum--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. US 7,014,707 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

582062v1

No. of add'l. copies

@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

0211111

PATENT NO.

•

7,014,707 B2

DATED

March 21, 2006

INVENTOR(S) :

MITSUAKI AMEMIYA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 29**

Line 60, "wire3 33" should read --wires 33--.

### **COLUMN 30**

Line 6, "vacuum" should read --in a vacuum--.

### **COLUMN 31**

Line 9, "upward" should read --upwardly--.

### COLUMN 33

Line 2, "be" should be deleted.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,014,707 B2</u>

No. of add't. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

582062v1

ASIG 2 2006

### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

PATENT NO.

7,014,707 B2

DATED

March 21, 2006

INVENTOR(S) :

MITSUAKI AMEMIYA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 6

Line 26, "deposit" should read --be deposited--.

### COLUMN 9

Line 52, "is" (second occurrence) should read --are--;.

### COLUMN 10

Line 33, "is continued being descended" should read --continues to descend--;

Line 34, "occure" should read --occur--;

Line 35, "not" should read --not only--; Line 65, "of" should be deleted; and

Line 67, "of" should be deleted.

### COLUMN 12

Line 1, "is escaped" should read --escapes--.

### **COLUMN 14**

Line 18, "is continued being descended" should read --continues to descend--.

#### COLUMN 18

Line 62, "vacuum" should read --in a vacuum--.

### COLUMN 19

Line 30, "vacuum," should read --in a vacuum--; and

Line 33, "vacuum" should read --in a vacuum--.

### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,014,707 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

582062v1

No. of add'l. copies @ 30¢ per page





### UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

7,014,707 B2

**DATED** 

March 21, 2006

INVENTOR(S) :

MITSUAKI AMEMIYA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 29**

Line 60, "wire3 33" should read --wires 33--.

### COLUMN 30

Line 6, "vacuum" should read --in a vacuum--.

### COLUMN 31

Line 9, "upward" should read --upwardly--.

### COLUMN 33

Line 2, "be" should be deleted.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

582062v1

PATENT NO. <u>US 7,014,707 B2</u>

